## Approved For Release 2002/06/17: CIA-RDP78B84747A002400060019-0

NPIC/TDS/D-1081-67 17 October 1967

MEMORANDUM FOR FILE	25X1
SUBJECT: Processor Acceptance	
	25X1
1067	25X1
1. On 3 October 1967  For the purpose of acceptance testing the	25X1
and sent	25X1
The highest was processor was processor	25X1
for subsequent feet and evaluation. The parameter a number and, after a number	25X1
checked out checked out performed very well, of minor adjustments to the air drier compartment, performed very well,	25X1
of minor adjustments to the dil recommended film types recommended film types recommended film types	25X1
As the result of this check day immediately install	25X1
shippedin the test area at the	25X1
the equipment, due to other instrumentation in the three time. It was installed sometime around 11 September 1967, with a representation.	25X1
time. It was installed sometime disclosed that the represen-	25X1
representative on hand (it was later disclosed that the installation without processing any film tative left immediately after installation date and 3 October 1967	
tative left immediately after installation without process 4967 thru the machine). Between the installation date and 3 October 1967 the technical monitor	
thru the machine). Between the installation and the date for ac-	25X1
several phone conversations were held regarding progress on the installation and the date for ac-	
were held regarding progress on the installation and of 3 October, the ceptance testing. When NPIC representatives arrived on 3 October, the	
ceptance testing. When NPIC representatives different was the machine discrepancies and performance were discussed. This was the machine discrepancies and performance were discussed. This was the	
first disclosure that the machine was not operating to process film	25X1
plant personnel had been machine definately out of ad-	25X1
for two weeks prior to the visit with the machine dering to the film justment. The impingement air in the dryer section was creating film justment. The impingement air in the top of the dryer entrance slot.	
iustment. The impingement all in the dry of the dryer entrance slot.	25X1
flutter and banging the film against the top of the dryor entrances flutter and banging the film against the top of the dryor entrances.  engineers stated they had tried all recommended adjustments for further recommendations,	
engineers stated they had cried that the recommendations, to alleviate the problem, had called for further recommendations, to alleviate the problem, had called for further recommendations,	25X1
1 1 - 1 orrow taken the driver section comprover of	
readjusted and reinstalled it to no avail.	

2. The NPIC representatives then went down to see the machine in operation and to observe the aforementioned film damage problem.

Declass Review by NIMA/DOD

## Approved For Reliense 2002 26/17 AA-RDP78B0-747A002400060019-0

The following deficiencies, in addition to film damage at the dryer were observed:

	a. Replenishment system inadequate for sensitometric testing (demand system). The system varies from 1 to 3 quarts of developer during the processing of 500 feet of film.	
	b. Foam build-up apparent in the wash section.	
25X1	c. would not dry thoroughly.	
	d. Positive pressure caused back-up of oxidized developer.	
	e. Speed control table (conversion chart) of little value - tachometer still required to determine film speed.	
	3. The technical representative immediately called to inform engineer	25X1
25X1	them that acceptance had not been accomplished and that an engineer should be sent in to immediately correct the problems. This was verbally agreed to	25X1
	October 1967 and made all the possible adjustments on the instrument. This resulted in a reduction but not elimination of the film damage and somewhat better drying characteristics than before. However, nothing was accomplished on dryer modification, replenishment system, over pressure, foaming wash tank, etc.	
25X1	4. On 11 October 1967 a call was made informed in detail of the processor deficiencies. His reaction was one of concern, since part of his job is follow-up on R&D efforts for possible commercial application. is unique, is	25X1 25X1
25X1	Since the processing principle used looking toward possibly making a shipboard type processor of the same looking toward possibly making a shipboard type processor of the same looking toward possibly making a shipboard type processor of the same	25X1
25X1	let me know of their decision on how to aleviate	
25X1 25X1	5. Since this was a Fixed Price contract, all the contract funding has been spent plus an estimated of the contractor's money. I called and advised him of the situation and to hold up any outstanding plilings and contract balance. This he agreed to do. He will also get on them regarding their lack of progress reports.	
25X1	6. called the technical monitor on 13 October 1967 and told him they had decided, if we would ship the machine back to to go over all the deficiencies, modify where necessary, and make	
25X1	to go over all the deficiencies, mourly whole notice to	

## Approved For Release 2002/06/17 CIA-RDP78B04747A002400060019-0

	sure we were fully satisfied with the machine. I told him, since the contract was completely out of funds, that I would attempt to send it back under a GBL.	
25X1		
25X1	7. Future testing of the Processor after completion of the rework, will probably be dependent upon the funding left in the T & M contract, since the Chip Printer and Chip Processor will have arrived for testing during the rework phase.	25X <sup>-</sup>
25X1		
		25X
	Distribution:	

Original - File

1 - Originator

2 - NPIC/TDS/DS